





KEY	
	No access to view structure
	Slight evidence of movement
	Negligible tilting
	Multiple slight cracking
	Moderate evidence of movement
	Moderate cracking
	Slight vertical displacement
	Slight horizontal displacement
	Slight tilt in buildings
	Moderate tilting in garden walls
	Slight bowing in walls
	Slight deformation of walls
	Significant evidence of movement
	Significant cracking
	Moderate tilting
	Moderate vertical displacement
	Moderate horizontal displacement
	Multiple bowed walls
	Rotation of structure
	Retaining Wall / Boundary Wall Damage

Based on Ordnance Survey 1:2500 mapping with the permission of the Controller of Her Majesty's Stationary Office. Crown Copyright.
Unauthorised reproduction infringes Crown Copyright and may lead to Prosecution in Civil proceedings.
Wrexham District Council Licence No. 14/086177

All geological, geomorphological and mining boundaries as well as overhead and mining ad locations should be considered approximate and should not be used for scaling.

NOTE:
Damage Survey Undertaken Spring 2004



Carl Longland
Head of Mobility and Development
Civic Offices, PO Box 212,
Telford TF3 4LB
DX:712122 Telford 5

**IRONBRIDGE GORGE INSTABILITY
IRONBRIDGE AND COALBROOKDALE
GROUND BEHAVIOUR STUDY**

STRUCTURAL DAMAGE SURVEY

Figure	Scale	High-Point Rendel
4.1	1:3000 @ A0	High-Point Rendel