

SJ ref	Site	Date	Investigation company	Report_subject
6603/32	validation report for tank removal at Dale End Garage	01/03/2008	Geotechnics Ltd	Contamination
6603/17	planning enquiry; land adjacent 59 Paradise, Coalbrookdale	31/08/2005	BTW	Geotechnical
6603/20	correspondence Re Loadcroft, Ironbridge - Mr Martin	08/05/2006	BTW	Geotechnical
6603/16	Preliminary Site Investigation at The Valley Hotel, Ironbridge	01/05/2005	Shire Consulting	Geotechnical&Contamination
6603/24	Enquiries re Loadcroft, Lincoln Hill, Ironbridge		BTW	Geotechnical&Contamination
6603/25	Initial enquiry re development at Dale End garage, Coalbrookdale	20/12/2005	E+R Engineers	Geotechnical&Contamination
6603/28	Geoenvironmental report for 8 dwellings, the valley hotel, buildwas rd	11/10/2007	GIP	Geotechnical&Contamination
6603/15	Slope Stability Report for the area surrounding The Valley Hotel, Ironbridge	01/05/2005	Shire Consulting	Stability
6603/18	Slope stability Information; Edge View, Station Road, Coalbrookdale	14/11/2005	Noah, Heeks & Partners	Stability
6603/21	Outline stability report at The Elms, Buildwas Road, Coalbrookdale	07/02/2006	Ground Investigation Specialists	Stability
6603/22	conservatory; Benbrook, Strethill Road, Coalbrookdale	16/06/2006	GIP	Stability
6603/23	Underpinning at 77 Bower Yard, Ironbridge	26/07/2006	Forkers	Stability
6603/26	Geotechnical investigation; land adjacent the Elms, Buildwas Road, Coalbrookdale	01/07/2006	GIS	Stability
6603/27	telephone enquiry re: development at 44 Paradise, Coalbrookdale	28/03/2007	BTW Engineers	Stability
6603/29	river bank instability; bower yard, ironbridge	20/07/2007	E&R Engineers	Stability
6603/31	retaining wall at Rotunda House, Lincoln Hill	11/10/2007	BTW Engineers/ Banbeck	Stability
6603/33	ground investigation report; Christina, Lincoln Hill	02/07/2008	Spilman Associates	Unclassified

SJ ref	Site	Date	Investigation company	Report_subject
6604/24	Ground investiagtion report for land adj. 34 Wellington Road, Horsehay	01/06/2007	Spilman Associates	Geotechnical&Contamin ation
6604/04	Planning Enquiry re 2 Church Road, Coalbrookdale	13/04/2005	Keith Aldin	Stability
6604/05	Planning Enquiry/response re 17 Church Road, Coalbrookdale	13/04/2005	Keith Aldin	Stability
6604/06	Site visit to Coach Road Motors, Church Road, Coalbrookdale	23/03/2005	E+R Engineers	Stability
6604/07	Planning applications at 24 Darby Road, Coalbrookdale	17/07/2006	BTW	Stability
6604/08	Coppice House, Coach Road, Coalbrookdale stability assessmetn	27/07/2006	GIP	Stability
6604/09	land adjacent 6 Darby Road, Coalbrookdale	18/04/2007	BTW Engnieers	Stability
6604/10	Telephone conversation re plot of land adj 3 Station Road, Coalbrookdale	17/01/2007		Stability
6604/11	Retaining wall design, 3 Station Road, Coalbrookdale	02/12/2005	Terry Onions	Stability
6604/25	Site visit to 14 Church Road, Coalbrookdale	28/11/2007	E + R Engineers	Stability
6604/26	proposed retaining wall; 4 Woodview, Woodside, Coalbrookdale	04/09/2008	Armando Spangolo	Unclassified

3

SJ ref	Site	Date	Investigation company	
6605/14	Installation of an Air Curtain Burner at Stoneyhill landfill site - planning comments	04/09/2007	E + R Engineers	Contamination
6605/17	proposed ground gas investigation at Lightmoor, Telfrod	01/07/2007	Scott Wilson	Contamination
6605/16	Information re culvert: Silver Trees, Jiggers Bank, Coalbrookdale	15/12/2006	E + R Engineers	Flood
6605/09	Pre-planning enquiry; land off Cherry Tree Hill, Coalbrookdale	19/04/2006	E+R Engineers	Geotechnical
6605/10	Silver Trees - Ash Tip Geotechnical Assessmetn	06/07/2006	Key Geo Solution	Geotechnical
6605/11	pre planning enquiry - 2 Cherry Tree Hill, Coalbrookdale	26/06/2007	BTW Engineers	Stability
6605/12	proposed new SGCT offices, Darby Road, Coalbrookdale	29/06/2007	GIP	Stability
6605/13	mudflow and washout, loam hole dingle, coalbrookdale	29/06/2007	BTW Engineers	Stability
6605/15	stability assesement, 47 Darby Road, Coalbrookdale	29/07/2008	Ground INVestigation and Piling	Stability

[illegible]

SJ ref	Site	Date	Investigation company	
6703/111	phase 2 contamination study, land at hodgebower, ironbridge	11/05/2007	GIP	Site Investigation
6703/112	Pre Planning Enquiry, Severn Lodge, New Road, Ironbridge	08/05/2006	BTW	Correspondence
6703/83	Proposed extensions 14 Ladywood, Jackfield	10/06/2005	Martin Starbuck	Correspondence
6703/85	Planning enquiry at Sundorne, Hodgebower	22/06/2005	btw	Other
6703/90	planning enquiry at 14 Belmont Road, Ironbridge	15/02/2006	BTW	Correspondence
6703/82	Planning Enquiry re land at Lincoln Hill/ Hodgebower, Ironbridge	13/06/2005	BTW	
6703/84	Enquiry re potential residential development, adj Humay, Hodgebower	20/06/2005	BTW	Other
6703/101	Meeting Note - 56-56A Madeley Road, Ironbridge	07/08/2006	E&R Engineers	File Note
6703/109	Information re limestone beneath "Woodlands, Lincoln Hill"	19/04/2007	Strata Test Ltd	Desk Study
6703/116	correspondence re foundations at 4 The Woodlands, Ironbridge	14/05/2007	PH Smith/ BTW Engineers	Correspondence
6703/118	Collapse in garden of 54 Belmont Road, Ironbridge	11/07/2007	E&R Engineers	File Note
6703/129	shallow mining stabilisation; 4a Woodlands Road, Ironbridge	04/12/2007	M&J Drilling	Treatment
6703/134	new dwellings at Riversmead Waterloo Street Ironbridge	08/05/2008	E + R Engineers	Correspondence
6703/75	Information re The Reynolds Tunnel, Ironbridge	21/02/2005	The Gorge Parish Council	Correspondence
6703/81	Planning Enquiry re The Mount House, Madeley Road, Ironbridge	13/04/2005	Keith Aldin	Correspondence
6703/100	Telephone Note - land to rear 49 Hodgebower, Ironbridge	21/06/2006	E&R Engineers	File Note
6703/102	Telephone Note - Rose Cottage, Waterloo Rd, Ironbridge	16/08/2006	E&R Engineers	File Note
6703/103	Telephone Note - The Mount House, Madeley Rd, Ironbridge	18/08/2006	E&R Engineers	File Note
6703/104	Planning application at 65 MillHouse, Bridge Bank, Ironbridge	03/10/2006	E&R Engineers	Correspondence
6703/105	Correspondence re Ladywood House, Ironbridge Road, Ironbridge	17/10/2006		Correspondence
6703/106	Proposed replacement balcony; 12 Belle Vue Road, Ironbridge	15/12/2006	Richard Goodson Architects	Correspondence
6703/107	pre planning enquiry re land opposite 9 Belle Vue Road, Ironbridge	08/02/2007	Engineers	Correspondence
6703/108	Pre planning enquiry re Riversmead, Waterloo St, Ironbridge	16/04/2007	BTW Engineers	Correspondence
6703/110	proposed conservatory; 10 Severn Bank, Ironbridge	18/05/2007	E&R Engineers	Correspondence
6703/113	telephone conversation re land movment adj Brackenwood, Barnett Leasows			File Note
6703/114	Telephone note re proposed extension at 11 Hillside, Ironbridge	06/10/2006		File Note
6703/115	Telephone conversation re propsoed extension at 4a The Woodlands, Ironbridge	15/01/2007		File Note
6703/117	pre planning enquiry - 1 Chapel Road, Ironbridge	19/06/2007	BTW Engineers	File Note
6703/119	collapsed retaining wall, The Old Chapel, 21 Madeley Road, Ironbridge	11/07/2007	Tom Keating & Associates Ltd	Correspondence

6

SJ ref	Site	Date	Investigation company	
6704/12	Ground investigation at Woodside West 1	10/04/2006	Geotechnical Engineering Ltd	Geotechnical&Contamination
6704/10	Proposed extension 15 Paradise, Coalbrookdale	05/09/2005	BTW	Stability
6704/13	landslip at Church Road, Coalbrookdale	26/06/2007	BTW Engineers	Stability
6704/14	Coabrookdale Youth Hostel stability report	04/06/2007	Shire Consulting	Stability

14-12



SJ ref	Site	Date	Investigation company	
6803/46	Brief land quality desk study re. Land at Timsbury, Wrekin View, Madley	01/03/2006	abs design	Contamination
6803/42	Planning Enquiry - 41 Coalford, Jackfield	17/08/2005	Martin Starbuck	Geotechnical
6803/47	Planning enforcement correspondence - Rookery Nook, Chapel Road, Jackfield	16/06/2006	E + R Engineers	Geotechnical&Contamin
6803/54	pre planning enquiry at 48 Coalford, Jackfield	28/03/2005	E & R Engineers	Geotechnical&Contamin
6803/39	Correspondence re retaining structures at 47 Wesley Road, Ironbridge	28/02/2005	Environment & Economy	Stability
6803/43	Proposed extensions, 40 Coalford, Jackfield	10/11/2005	Tony Rowland	Stability
6803/48	Telephone conversation - 44 Coalford, Jackfield	05/07/2006	BTW Engineers	Stability
6803/49	Telephone Note - Ainsworth House, Barnett Leasows	01/06/2006	E&R Engineers	Stability
6803/50	Telephone Note - The Bird In Hand Pub, Ironbridge	23/08/2006	E&R Engineers	Stability
6803/51	Telephone conversation re prospective development at 8 Chapel Road, Jackfield	09/08/2006	E+R Engineers	Stability
6803/52	Proposed side extension @ Tara, The Knowle, Jackfield (appeal)	20/11/2006	BTW Engineers	Stability
6803/55	telephone conversation re potential purchase of 84 Lloyds Head, Ironbridge	09/05/2007		Stability
6803/56	Telephone conversation re Crossing Cottage, Jackfield	23/07/2006		Stability
6803/57	Site meeting at 129 Calcutts, Jackfield	14/09/2007		Stability
6803/58	Slope stability and mining investigation; 7 Chapel Road, Ironbridge	15/06/2007	Ground Investigation and Piling Ltd	Stability
6803/60	instability problem at 126 The Calcutts, Jackfield	18/03/2008	BTW Engineers	Stability
SJ ref	Site	Date	Investigation company	Report_subject

**Table E1 Inspected Planning records**

Planning Ref.	Site	Comments	Zone
SJ6603/18	Edge View, 6 Station Road	Preliminary report. Retaining wall collapse.	2
SJ6603/26	Elms, Buildwas Road	GI - including BH logs and shear tests	2
SJ6603/28	Valley Hotel Housing Development	2 GI reports including BH logs and chem testing	2
SJ6603/31	Rotunda House, Lincoln Hill (unsure of exact location)	Planning application only	3
SJ6603/32	Dale End	GI (Tank Clearance and Validation Testing) and planning application	1
SJ6603/33	Christina, Lincoln Hill	GI, Desk Study and Geotechnical Report	4
SJ6605/10	Silver Trees (Greenbank Farm), Jiggers Bank	Report from 2006 - claiming Jiggers bank is stable enough to remove PFA from pit.	4
SJ6605/13	Loamhole Dingle, mudflow	illegible records	
SJ6703/124	Woodlands, Lincoln Hill	GI report - revealed mine workings below site (inc logs)	3
SJ6703/126	Old Gas Works Site between Madeley Road and Waterloo Street	6 BH records - no record of instability	3/4
SJ6703/127	Jockey Bank	4 BH records - no record of instability	4
SJ6703/128	Old Gas Works Site between Madeley Road and Waterloo Street	4 BH records - no record of instability	3/4
SJ6703/129	4a Woodlands, Lincoln Hill	5 BH - stabilisation of mine workings	3
SJ6703/130	3 Ladywood	Site location plan only	4
SJ6703/131	The Library House, 11 Severn Bank	Planning application only	3
SJ6703/132	56 Madeley Road	Planning application only	3/4
SJ6703/133	19 Jockey Bank	Slope stability assessment	3
SJ6703/134	Riversmead, Waterloo Street	Planning application only	3
SJ6703/48	28 Barnetts Leasows, Jackfield	Planning application only	4
SJ6703/59	Bath Road - Proposed Guest House	Planning application, construction plans, stability assessment, stability analysis and GI. Conc. - no evidence of potentially significant ground instability	3/4
SJ6703/78	10 Hillside	CA report - possible mine workings below site, envirocheck report	4
SJ6703/87	3 Hodge Bower	Phase 2 GI report - mainly geo-environmental	3
SJ6703/111	off Hodge Bower	Phase 2 GI report - mainly geo-environmental	3
SJ6803/02	37 Lloyds Mount	Radar Survey (1989). Conc. - possible mineshaft found beneath the patio area to the east of the building.	5
SJ6803/58	7 Chapel Road	Planning application	3/4