


- Convex break in slope (sharp)
- Convex break in slope (smooth)
- Concave break in slope (sharp)
- Concave break in slope (smooth)
- Change in slope, unable to distinguish slope morphology at mapping scale
- Lobate feature
- Tension Crack
- Slope angle and direction (slope angle in degrees)
- Undulating slope angle and direction (slope angle in degrees)
- Exposed Bedrock
- Boulders
- Stream and flow direction
- Wet ground
- Pond
- New Development

- Telford and Wrekin Borough Boundary
- World Heritage Site Boundary

A	JUN 09	WORK MEASUREMENTS - CLIENT REQUEST	DJW	DHR	JA
0	DEC 08	REPORT	DJW	DHR	JA
Rev	Rev, Date	Purpose of revision	Drawn	Checked	Approved

JACOBS
Holliswood House, Stafford Court, Stafford Park 1, Telford, UK TF3 3DD
Tel: +44(0)1952 296500 Fax: +44(0)1952 296501
www.jacobs.com



Project
IRONBRIDGE GORGE
GEOMORPHOLOGICAL MAPPING

Drawing title
LINE GEOMORPHOLOGY MAP
STUDY AREA
SJ 6702 - 6802

Drawing status
REPORT

Scale	1:3000 @ A1	DO NOT SCALE
Jacobs No.	BT100T100	
Client no.	-	

Drawing number	Rev
1100100/G	A

This drawing is not to be used in whole or part other than for the intended purpose and project as defined on this drawing. Refer to the contract for full terms and conditions.