


- Convex break in slope (sharp)
- Convex break in slope (smooth)
- Concave break in slope (sharp)
- Concave break in slope (smooth)
- Change in slope, unable to distinguish slope morphology at mapping scale
- Lobate feature
- Tension Crack
- Slope angle and direction (slope angle in degrees)
- Undulating slope angle and direction (slope angle in degrees)
- Exposed Bedrock
- Boulders
- Stream and flow direction
- Wet ground
- Pond
- New Development

A	JUN 09	WORK AGREEMENTS - CLIENT REQUEST	DJW	DHR	JA
0	DEC 08	REPORT	DJW	DHR	JA
Rev	Rev / Date	Purpose of revision	Drawn	Checked	Approved

JACOBS

Telford & Wrekin

COUNCIL

Hollwood House, Stafford Court, Stafford Park 1, Telford, UK, TF3 3DD
Tel: +44(0)1952 296500 Fax: +44(0)1952 296501
www.jacobs.com

Project
IRONBRIDGE GORGE
GEOMORPHOLOGICAL MAPPING

Drawing title
LINE GEOMORPHOLOGY MAP
STUDY AREA
SJ 6505 - 6605

REPORT		
Drawing status	Scale	DO NOT SCALE
Jacobs No.	BT100T100	
Client no.	-	
Drawing number	1100100/G	Rev A
This drawing is not to be used in whole or part other than for the intended purpose and project as defined on this drawing. Refer to the contract for full terms and conditions.		

Reproduction from the Ordnance Survey Map with the permission of the controller of Her Majesty's Stationery Office. Crown Copyright. Reproduced by permission. All Rights Reserved.