


- Convex break in slope (sharp)
- Convex break in slope (smooth)
- Concave break in slope (sharp)
- Concave break in slope (smooth)
- Change in slope, unable to distinguish slope morphology at mapping scale
- Lobate feature
- Tension Crack
- Slope angle and direction (slope angle in degrees)
- Undulating slope angle and direction (slope angle in degrees)
- Exposed Bedrock
- Boulders
- Stream and flow direction
- Wet ground
- Pond
- New Development

- Telford and Wrekin Borough Boundary
- World Heritage Site Boundary



Project
IRONBRIDGE GORGE
GEOMORPHOLOGICAL MAPPING

Drawing title
LINE GEOMORPHOLOGY MAP
STUDY AREA
SJ 6503 - 6603

Drawing status
REPORT

Scale	1:3000 @ A1	DO NOT SCALE
Jacobs No.	BT100100	
Client No.	-	

Drawing number	1100100/G	Rev	A
----------------	-----------	-----	---

This drawing is not to be used in whole or part other than for the intended purpose and project as defined on this drawing. Refer to the contract for full terms and conditions.

Rev	Rev. Date	Purpose of revision	Drawn	Checked/Approved
A	JUN 09	IMPROVEMENTS - CLIENT REQUEST	DMW	DHR
0	DEC 08	REPORT	DMW	DHR
Rev	Rev. Date	Purpose of revision	Drawn	Checked/Approved

JACOBS
Hollwood House, Stafford Court, Stafford Park 1, Leek, UK TF3 3DD
Tel: +44(0)1952 236500 Fax: +44(0)1952 236501
www.jacobs.com



Client
IRONBRIDGE GORGE
GEOMORPHOLOGICAL MAPPING